

# WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 0

33/2/5L

Water Right Permit No. \_\_\_\_\_

(1) OWNER: Name SUNRISE Hills Community Assoc Address 582 E SUNRISE BLVD, OAK HARBOR WA 98271

(2) LOCATION OF WELL: County ISLAND NE 1/4 SW 5 T. 33 N. R. 2E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) SUNRISE Blvd OAK HARBOR WA 98271

(3) PROPOSED USE: ☒ Domestic ☐ Industrial ☐ Municipal ☒  
☐ Irrigation ☐ Test Well ☐ Other ☐  
☐ DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) 2  
Abandoned ☐ New well ☒ Method: Dug ☐ Bored ☐  
Deepened ☐ Cable ☒ Driven ☐  
Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.  
Drilled 282 feet. Depth of completed well 282 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6 " Diam. from 0 ft. to 272 1/2 ft.  
Welded ☒ " Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Liner installed ☐ " Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
Threaded ☐ " Diam. from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Perforations: Yes ☐ No ☒

Type of perforator used \_\_\_\_\_

SIZE of perforations \_\_\_\_\_ in. by \_\_\_\_\_ in.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.  
\_\_\_\_\_ perforations from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Screens: Yes ☒ No ☐

Manufacturer's Name Johnson  
Type STAINLESS Model No \_\_\_\_\_  
Diam. 6 Slot size 15 from 272 ft. to 278 ft.  
Diam. 6 Slot size 20 from 278 ft. to 282 ft.

Gravel packed: Yes ☐ No ☒ Size of gravel \_\_\_\_\_  
Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.  
Material used in seal BENTONITE

Did any strata contain unusable water? Yes ☐ No ☒  
Type of water? \_\_\_\_\_ Depth of strata \_\_\_\_\_  
Method of sealing strata off \_\_\_\_\_

(7) PUMP: Manufacturer's Name \_\_\_\_\_  
Type: \_\_\_\_\_ H.P. \_\_\_\_\_

(8) WATER LEVELS: Land-surface elevation \_\_\_\_\_ ft.  
Static level 225 ft. below top of well Date 12-92  
Artesian pressure \_\_\_\_\_ lbs. per square inch Date \_\_\_\_\_  
Artesian water is controlled by \_\_\_\_\_ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level  
Was a pump test made? Yes ☐ No ☒ If yes, by whom? \_\_\_\_\_

Yield \_\_\_\_\_ gal./min. with \_\_\_\_\_ ft. drawdown after \_\_\_\_\_ hrs.

\_\_\_\_\_ " " " " " "

\_\_\_\_\_ " " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time Water Level Time Water Level Time Water Level

Date of test \_\_\_\_\_

Bailer test 20 gal./min. with 15 ft. drawdown after 4 hrs.

Airtest \_\_\_\_\_ gal./min. with stem set at \_\_\_\_\_ ft. for \_\_\_\_\_ hrs.

Artesian flow \_\_\_\_\_ g.p.m. Date \_\_\_\_\_

Temperature of water \_\_\_\_\_ Was a chemical analysis made? Yes ☐ No ☒

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
DIMTY GRAVEL	0	5
HARD PAN	5	47
GRAVELY HARD PAN	47	156
HARD GRAVEL	156	168
HARD PAN	168	187
GRAVELY	187	204
SANDY CLAY	204	267
WATER GRAVEL MIX	267	282

RECEIVED

DEC 23 1992

DEPT. OF ECOLOGY

Work started DEC 1992 Completed DEC 20 1992

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME WHIDBEY WELL DRILLERS  
(PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address OAK HARBOR WA.

(Signed) Donna Fisher License No. 129  
(WELL DRILLER)

Contractor's  
Registration No. WAIDBUD289MM Date DEC 1992

(USE ADDITIONAL SHEETS IF NECESSARY)